


OPTIMA 50 + bouton Ø6mm Spécial rénovation



SIAMP

Monaco


- (A) : Ø de 6
à 18 mm
(D) : Ø de 58
à 72 mm
(B) : 302 mm mini.
à 465 mm max.
(C) : de 149 mm
à 245 mm




**Ne pas utiliser de pâtes
à joints**




1



2



3




4





H	K
De Ø 6 à 18 mm	
≥ 362	
$357 \geq 362$	A / B
$352 \geq 356$	B / C
$347 \geq 351$	C / D
$342 \geq 346$	D / E
$337 \geq 341$	E / F
$332 \geq 336$	F / G
$327 \geq 331$	G / H
$322 \geq 326$	H / I
$317 \geq 321$	I / J
$312 \geq 316$	J / K
$307 \geq 311$	K / L
$302 \geq 306$	L / M

5













NB : Un serrage excessif peut entraîner une détérioration du mécanisme qui ne serait pas couverte par la garantie.

NB : Pour un bon fonctionnement le câble doit être parallèle aux parois du réservoir




6








12






14




13




15




MAINTENANCE







2 EN 1




INSTALLATION







MAINTENANCE



2 EN 1



INSTALLATION



MAINTENANCE

