








SIAMP

Monaco


Compact 100
AS/NZS 3500.1

Compact 100 OD
(Delayed action)






Universel inlet valve
for low entry cisterns,
from 284 mm height.




MAINTENANCE 1




In case the tank does not refill quickly, you need to rinse the filter or reducer




MAINTENANCE 2/A




MAINTENANCE 2/B



MAINTENANCE 2/C



MAINTENANCE 2/D



INFORMATION

Close water supply before in case of inlet replacement or servicing.

Do not over tight in any case.

Do not use any sealing paste and/or compound in any case.

High toxicity or abrasive cleaners are not to be used into the tank.

Operating pressure :

Low pressure version : from 0.2 to 5 bars

High pressure version : from 0.5 to 16 bars

Check water tightness before opening water supply.

SIAMP

Monaco

4, quai Antoine 1er - BP 219

MC 98007 MONACO Cedex

Tél : +377 93 15 53 75

Fax : +377 92 05 71 04

contact@siamp.com / www.siamp.com