




VERSÒ BCS 800 PN




Remplacement du mécanisme pneumatique
Pneumatic flush valve replacement


AVANT - BEFORE




APRES - AFTER




1




2




3



4






5





AVANT - BEFORE




APRES - AFTER



1-a



1-b



2

